



SERVICE KIT SERVO VALVE PS

Artikelnummer: HS5196

675,00 kr

PRODUKTBESKRIVNING

Service kit för SeaStar HC5801 & HC5803

PRODUKTSPECIFIKATION

Passar: HC5801 & HC5803

Samtliga kit krävs.
HS5196, HS5197 & HS5198